

Superb Services Group

98811 Highway #1
Ingleside, Ohio 45688

QUOTE

Reference number: **SC02-647**
Customer reference: PO#19398
Resource: George - Van 9804
Page number: 1 of 1

Billing address:

Abcon Manufacturing Inc.

240 Jefferson Ave.
Cincinnati, Ohio 45243
USA

Site address:

Abcon Manufacturing Inc.

Attn: Richard Warren
240 Jefferson Ave.
Cincinnati, Ohio

Work Description

Repair leaking faucet. (Not included in Quote)

Work for new mop sink, faucet, water lines and waste line. To be completed Friday.

Material Description

Material Description	Qty
2 CI NO HUB SOIL PIPE	10.00
2 NO HUB 1/4 BEND	2.00
2 NO HUB COUPLING	6.00
2 CI NO HUB WYE	1.00
1/2 COPPER TYPE L HARD PIPE	40.00
1/2 WROT COPPER 90	6.00
3/4x3/4x1/2 CxGxC WROT REDU TEE	2.00
SINK SERVICE W/TRAP STD	1.00
MOP SINK FAUCET SET	1.00

Summary

		Total (\$)
Subtotal Material		619.19
Subtotal Labor		715.00
Service Van (per hour)	(10.00 @ \$7.50)	75.00
Permit	(1.00 @ \$27.50)	27.50
Overhead	(@ 10.000 %)	143.67
Markup	(@ 10.000 %)	158.04
Subtotal		1,738.40
Cincinnati City Tax	(@ 1.000 %)	17.38
State Tax	(@ 5.000 %)	86.92
Total (not to exceed \$2,000.00 before taxes)		\$1,842.70

Terms

Our price is valid for 30 days and subject to changes any time thereafter.

Rep. Name: _____
Date: _____
Signature: _____
I hereby propose the above described work.

Client Name: _____
Date: _____
Signature: _____
I hereby accept the terms of the above described work.

Superb Services Group

98811 Highway #1
Ingleside, Ohio 45688

WORK ORDER

Reference number: **SC02-647**
Job date: Jul. 10, 2002
Customer reference: PO#19398
Resource: George - Van 9804

Billing address:

Abcon Manufacturing Inc.
240 Jefferson Ave.
Cincinnati, Ohio 45243
USA

Site address:

Abcon Manufacturing Inc.
Attn: Richard Warren
240 Jefferson Ave.
Cincinnati, Ohio
Tel: 513-555-4000

Site Notes

Always enter from service door, check with Mr. Warren before proceeding with any work.

Work Description

Repair leaking faucet.

Look at work for new mop sink, faucet, water lines and waste line and prepare quote. Talk to Bob Ryan. To be completed Friday.

Work Performed

Materials	Qty

Labor	Reg Hrs	OT Hrs

Other Charges	Qty

Name: _____
Date: _____
Signature: _____

I hereby acknowledge the satisfactory completion of the above described work.

Superb Services Group

98811 Highway #1
Ingleside, Ohio 45688

INVOICE

Invoice number: 2002-82
Invoice date: Jul. 10, 2002
Reference number: SC02-647
Customer reference: PO#19398
Resource: George - Van 9804
Page number: 1 of 1

Site address:

Abcon Manufacturing Inc.

240 Jefferson Ave.
Cincinnati, Ohio 45243

Abcon Manufacturing Inc.

Attn: Richard Warren
240 Jefferson Ave.
Cincinnati, Ohio

Work Description

Repair leaking faucet.
Resolution: Hot was leaking. Replaced Hot and Cold stems as per Mr. Warren's instructions.

Installed new mop sink, faucet, water lines and waste line as per quote.

Material Description	Qty	Price	U	Total (\$)
2 CI NO HUB SOIL PIPE	10.00	654.00	C	65.40
2 NO HUB 1/4 BEND	2.00	9.54	E	19.08
2 NO HUB COUPLING	6.00	9.72	E	58.32
2 CI NO HUB WYE	1.00	12.36	E	12.36
1/2 COPPER TYPE L HARD PIPE	40.00	1.36	E	54.40
1/2 WROT COPPER 90	6.00	0.71	E	4.26
3/4x3/4x1/2 CxCxC WROT REDU TEE	2.00	2.58	E	5.16
SINK SERVICE W/TRAP STD	1.00	292.22	E	292.22
MOP SINK FAUCET SET	1.00	107.99	E	107.99
039029(300108) RH STEM	1.00	13.28	E	13.28
039030(300107) LH STEM	1.00	13.28	E	13.28

Total Material

\$645.75

Summary

			Total (\$)
Subtotal Material			645.75
Journeyman Mechanic	(16.00 Hrs @ \$55.00)		880.00
Service Van (per hour)	(16.00 @ \$7.50)		120.00
Permit	(1.00 @ \$27.50)		27.50
Overhead	(@ 10.000 %)		167.33
Markup	(@ 10.000 %)		184.06
Subtotal			2,024.64
Adjustment			-24.64
Cincinnati City Tax	(@ 1.000 %)		20.00
State Tax	(@ 5.000 %)		100.00

Total

\$2,120.00

Terms

Net 30 days, 2% discount 10 days.